



Tech Info Library

PC Setup Control Panel: Version Change History (9/95)

Article Created: 21 July 1995

Article Reviewed/Updated: 28 September 1995

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

This article describes the different versions of the PC Setup control panel and provides a description of the changes implemented with each version.

DISCUSSION -----

Begin_Table

Software Versions:

-
- 1.0.1 • First release, and is intended for the Macintosh Quadra 610 DOS Compatible only.
 - 1.0.2 • Distributed in System Update 3.0 and System 7.5 Update 1.0.
 - Intended only for the Macintosh Quadra 610 DOS Compatible.
 - Fixes a video interference problem when using a single 14" display.
 - 1.0.3 • Support for the Power Macintosh 6100 DOS Compatible added.
 - 1.0.5 • Added support for the Macintosh LC and Performa 630 DOS Compatible.
 - Added Copy/Paste support for two-byte languages (Japanese localization).
 - Enabled Cyrix write-back cache. If Cyrix parts are part of the hardware platform, write-back cache is automatically enabled. A separate application is available to disable this functionality.
 - PC Translators added support for correct Mac/Windows translation of two-byte characters under the Japanese Script System. Resolved with the two-byte cut/paste support.
 - No longer can you use "*" as a drive label.
 - Fixed Problem restarting a DOS Compat system with CD inserted in the CD-ROM drive on the DOS side.
 - Fixed problem with unreadable characters appearing in the Controls Panels window after the "About..." message is closed.
 - Fixed problem with the hot key field being de-selected when Japanese characters are input.

- Edited contents of Balloon Help for "Launch PC" to make more generic.
- Fixed problem with DOSClip when attempting to paste in PC Paintbrush
- Strings in "PC Print Spooler", "PC Clipboard" lengthened.

- 1.0.6
- Support added for two-byte printing (Japanese localization).
 - Fixed problem with CD-ROM driver not properly handling the open and close messages.
 - Fixed problem with meaningless document printing when "Chev us" is executed on the DOS side.
 - Fixed problem with inability to input from keyboard after switching from the Macintosh side.
 - Two-byte character printing in DOS environment added.
 - Two-byte characters support in DOS environment.
 - Fixed problem with File dialog not closing when selection was made.
 - Removed the "PC Network: AgentOpen () returned -1" message from appearing when AppleTalk was turned off.
 - Fixed problem with changes made to PC Setup not activated from a warm start up on DOS Side.
 - Fixed problem with system freezing when switching environments during launch of Print Monitor.
 - Fixed problem with Print Spooler which caused system freeze.
 - Fixed problems with unreadable characters in the beginning of a document.
 - Fixed problem where a 1-byte space was followed by a two-byte character could not be copied or pasted correctly.
 - Fixed problem with two-byte character printing, which printed unreadable characters when a QuickDraw drivers exists for the Macintosh and the Epson driver exists on the PC.
 - Escape sequence supported added for Epson printers used in Japan.
- 1.0.7
- Changed version strings. Unified code for Power Macintosh 6100 DOS Compatible, LC 630 DOS Compatible and Performa 640 DOS Compatible (includes localization support).

End_Table

Article Change History:

- 28 Sep 1995 - Corrected minor typo.
- 27 Jul 1995 - Corrected technical information

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: ktable,supt

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 18233