



Tech Info Library

Power Macintosh 5200: Rev A/Rev B Video Connectors (5/96)

Article Created: 15 April 1996

Article Reviewed/Updated: 14 May 1996

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I'm attempting to adjust the on-screen video for a customer's Power Macintosh 5200 computer. However, the instructions on card 28 in the On-Screen Video section of the Adjustments chapter state to locate jumper P805. However, there does not appear to be a jumper P805 on this analog board. What should I do?

DISCUSSION -----

There is an error in the Service Source CD. On the Rev B Power Macintosh 5200 analog board there is no P805 jumper connector. Instead, the video adjustment connection is at jumper location P102, which is near the logic board connector on the lower left-hand corner of the analog board. You can follow the instructions in the Service Source CD using P102 in place of P805.

The following computers may be affected by this:

- Macintosh 5200CD family: Macintosh 5200/75 LC, Performa 5200, Performa 5210, Performa 5215, and Performa 5220.
- Macintosh 5300CD family: Macintosh 5300/100 LC, Performa 5300.

Article Change History:

14 May 1996 - Made title more descriptive.

Copyright 1996, Apple Computer, Inc.

Keywords: kmanerr,hts

=====

This information is from the Apple Technical Information Library.

19960514 15:31:29.00

Tech Info Library Article Number: 19614