



# Tech Info Library

## Power Macintosh: Incorrectly Labeled Processor Cards (1/97)

Article Created: 29 January 1997

Article Reviewed/Updated: 30 January 1997

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

TOPIC -----

A limited number of the first Power Macintosh 7300, 7600/200, 8600 and 9600 systems were shipped with processor cards that were incorrectly labeled with a use restriction label that says "8500/9500 only".

DISCUSSION -----

All processor cards shipped in the Power Mac 7300, 8600, and 9600 computers DO NOT carry a usage restriction. If the assembly number on your processor card matches one of the following part numbers then disregard the use restriction label; it is incorrect.

Begin\_Table

DESCRIPTION	ASSEMBLY PART NUMBER
PowerPC 604e 180MHz	630-2240, 630-2249
PowerPC 604e 200MHz	630-2201, 630-2204, 630-2250

End\_Table

Customers may call Apple to report that they were shipped Power Mac systems with the wrong processor card installed. If the processor card matches one of the assembly numbers listed above then the processor card was incorrectly labeled and customers should ignore the label.

Service Providers ordering either a replacement 180MHz processor card (p/n 661-1305), or a 200MHz processor card (p/n 661-1307) may also receive a processor card that is incorrectly labeled. If the replacement processor card contains one of the assembly numbers listed above then the processor card was incorrectly labeled and therefore the label should be ignored.

Unauthorized disclosure of this information could cause a temporary loss of confidence by the customer base or provide a basis for negative publicity.

Article Change History:

30 Jan 1997 - added 630-2204 part number to table.

Copyright 1997, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

ArticleID: TECHINFO-0020900

19970131 08:04:39.00

Tech Info Library Article Number: 20900