



Tech Info Library

Service Hard Drives: Why Some Are Named Test0_HDA

Article Created: 7 December 1992

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I have just received a Service drive from Apple that was pre-formatted with the name "Test0_HD". Why did this occur?

DISCUSSION -----

Apple's Service Module hard drives are extensively tested but not formatted before they are sent to Apple Service Providers. Occasionally, Apple Service performs an additional spot check to these hard drives at Apple or at the hard drive vendor. During this test, the hard drives are formatted and named "Test0_HD". These hard drives operate properly and don't need to be reformatted before you install System Software.

If a hard drive has System Software installed, the drive's name would change from "Test0_HD" to "Macintosh HD".

Copyright 1992, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11069