



# Tech Info Library

## TV Tuner Card Picks Up The Same Channel (11/96)

Article Created: 25 November 1996

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

TOPIC -----

The Apple Video Player on my Macintosh Performa 5200 works for a while and then channels 14 through 21 all start to receive the same channel.

This issue was rectified by a new TV Tuner Card before, not by installing clean System or application software.

DISCUSSION -----

This issue was resolved by reworking the TV Tuner Cards a year ago, and purging service stocks. Current service stock should have revised TV Tuner Cards. If the new card should fail, let Apple know immediately.

Copyright 1996, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19961126 07:56:17.00

Tech Info Library Article Number: 20674