



# Tech Info Library

## Sound In Options: Dimmed on Some Macintosh Models (7/95)

Article Created: 16 February 1995

Article Reviewed/Updated: 24 July 1995

TOPIC -----

I've got a problem with a Quadra 800 and Sound Manager 3.0. When I open the Sound control panel (v. 8.0.1) and I choose Sound In, the Options button is disabled (it appears dimmed or "grayed out"). Do you know what could be causing this?

DISCUSSION -----

The Options button was added to the Sound control panel to provide a place for users to control access to sound channels and the Playthrough option. The affected models released before these options were put into use.

The systems that exhibit this behavior are:

- Performa 475/476
- Quadra 605
- Centris 610
- Centris 650
- Quadra 610
- Quadra 650
- Quadra 800

When these computers were released, the CD-ROM drive was set up to always play audio CDs through the built-in speaker (or the sound out port). The CD player was chosen as the sound source whenever the microphone was not plugged into the Sound In port. In other words, the features that you control by clicking on the Options button are controlled automatically on these systems.

There is no way to let these systems control their sound channels and playthrough options using software, like other Macintosh systems do. That is why the Options button has been disabled.

Article Change History:

24 Jul 1995 - Added additional computers

06 Mar 1995 - Added keyword; made minor technical updates.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Keywords: kalley

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17206