

Apple TV/FM Radio System: Which Video-in Card to Use? (8/96)

Article Created: 8 August 1996 Article Reviewed/Updated: 9 August 1996
TOPIC
I want to install the Apple TV/FM Radio Tuner System (M4586LL/A) in my computer but I have an earlier version of the Apple Video System (video-input card). Do I need to upgrade to the latest Apple Video System, part number M2894LL/D?
DISCUSSION
The Apple TV/FM Radio Tuner System (M4586LL/A) was tested with all previous revisions of the Apple Video System and is backwards compatible with them.
Depending on your computer, you may need a new rear I/O Door which has the necessary access holes for both antennas. You need to ask an Apple-authorized service provider to order this for you. The Apple service part number for the rear I/O Door is 922-2190.
This article was published in the Information Alley on 8 August 1996.
Article Change History: 09 Aug 1996 - Added alley information.
Copyright 1996, Apple Computer, Inc.
Keywords: kppc,kcompat,kalley
This information is from the Apple Technical Information Library.
19960812 06:56:12.00

Tech Info Library Article Number: 20265