

## VideoSync: Avoiding Flicker when Video Taping a Macintosh (3/95)

Article Created: 22 December 1991 Article Reviewed/Updated: 28 March 1995

TOPIC -----

This article desbribes VideoSync, a product which eliminates flicker when video taping the image on a Macintosh monitor.

DISCUSSION -----

VideoSync is a utility designed to allow the video recording of Macintosh monitor images with consumer or professional video camera equipment. VideoSync supports the Macintosh Display Card 4.8, 8.24, 8.24 GC, Apple High Resolution Video Card, and the Macintosh II Video Cards when connected to an AppleColor High Resolution RGB or monochrome monitor or Macintosh 12-inch RGB Display.

The utility is an extension to the Monitors control panel that adjusts the timing of the Apple display card so that the monitor image appears stable when viewed by an external NTSC camera. VideoSync does not create RS-170A timing for directly recording Macintosh screens to VCR. VideoSync can be licensed as a stand-alone utility for video integration applications, or serve as a platform on which to add other video timing alternatives.

The VideoSync utility is not compatible with Power Macintosh and Quadra AV computers. See the Tech Info Library article titled "VideoSync: Not Supported on Power Macintosh" for additional information on compatibility with the Power Macintosh and Quadra AV computers.

VideoSync is available through online services Apple publishes software updates on.

These articles can help you locate software updates mentioned here:

- Where To Find Apple Software Updates Lists online services for "free" Apple software updates

- Obtaining Apple Product Support in the USA Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech. Info. Library

Article Change History:

28 Mar 1995 - Changed filming to video taping in title. 03 Mar 1995 - Added where to locate VideoSync.

Support Information Services Copyright 1991-95, Apple Computer, Inc.

Keywords: <None>

\_\_\_\_\_

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 9400