



# Tech Info Library

## Newton MessagePad 110: Not Recognizing Messaging Card (4/94)

Article Created: 18 April 1994

TOPIC -----

This article describes a problem with the Newton MessagePad 110 recognizing the Newton Wireless Messaging card.

DISCUSSION -----

If you are having problems with the Newton Wireless Messaging card being recognized, remove the spacer clip attached to the card underneath the battery compartment. This allows the card to make better contact with the PCMCIA slot. The spacer is needed on the card when it is used with the original MessagePad or the MessagePad 100.

Support Information Services  
Copyright 1994, Apple Computer, Inc

Keywords: KNMP

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15155