



Tech Info Library

AppleLink: Getting Help Programming CCL Files

This article last reviewed: 8 November 1989

TOPIC -----

My company has Rolm phone switches installed in all of our buildings, but we're having difficulty operating AppleLink across the Rolm switch.

I can modify my CCL file to send the appropriate attention code, but there is no recognition of the response from the switch. I discovered a work around--inserting a time delay, but what I really want is to test the line for the correct response. What to do?

DISCUSSION -----

AppleLink Operations has an AppleLink address, "CCL.SUPPORT", for questions and information about CCL files. If this is an urgent issue, call the AppleLink HelpLine at 408-974-3309.

Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 4848