



Tech Info Library

AudioVision: System 7.5 Requires AppleVision SW v1.0.1 (1/96)

Article Created: 24 April 1995

Article Reviewed/Updated: 25 January 1996

TOPIC -----

I just upgraded from System 7.1 to System 7.5, and noticed that my Sound control panel no longer shows the AudioVision option. I have reinstalled the AudioVision software using the Installer disk that originally came with my AudioVision 14 Display, but it did not solve this problem. How can I get the AudioVision option back?

DISCUSSION -----

Neither System 7.5 or System 7.5 Update 1.0 come with the required ~AudioVision extension you need. The supported display software for your monitor on a System 7.5.x computer is AppleVision Display Software 1.0.1. This software is available from online services.

These articles can help you locate software updates mentioned here:

- Where To Find Apple Software Updates
Lists online services for "free" Apple software updates
- Obtaining Apple Product Support in the USA
Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech. Info. Library

Article Change History:

25 Jan 1996 - Made title more descriptive.

14 Sep 1995 - Corrected minor typo.

05 Sep 1995 - Added AppleVision Display software information.

Support Information Services

Copyright 1995-96, Apple Computer, Inc.

Keywords: sys75

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17645