



Tech Info Library

Apple II/II+/IIe: Cable Compatibility (9/94)

Article Created: 27 September 1994

TOPIC -----

This article provides cable compatibility information for Apple computer systems and a variety of Apple peripherals.

The left column lists the peripherals, the right column lists the cable required to connect one of the following computers to it; Apple II, Apple II Plus, or the Apple IIe.

Part numbers which begin with a letter are the finished goods part number, the seven digit numbers are the service part numbers.

DISCUSSION -----

Peripheral -----	Cable part number -----
AppleFax Modem	N/A
Apple Personal Modem Apple Data Modem 2400	A2C0312/590-0555 (smoke) or A9C0314/590-0556 (w/jumper on Super Serial Card)
Apple Modem 300 Apple Modem 1200	A2C0354/590-0121
Apple ImageWriter II or II/L ImageWriter LQ	A9C0314/590-0556 (smoke) or LocalTalk or A2C0312/590-0555 (w/jumper to modem)
Apple ImageWriter Printer Apple ImageWriter 15"	A2C0352/590-0037
LaserWriter, Plus, IInt, IIntx, IIf, IIg LaserWriter Pro 600/630/810	LocalTalk (Req. WorkStation Card)

Personal LaserWriter NT, NTR

Personal LaserWriter LS N/A
StyleWriter & StyleWriter II
Color StyleWriter/Color StyleWriter Pro

Apple LaserWriter IIsc N/A
Personal LaserWriter SC

AppleCD SC M0206/658-8031 (SCSI System cable)•
Apple Hard Disk 20/40/80

Apple Tape Backup 40SC N/A
Apple Scanner
Apple Color OneScanner
Apple Color Printer

LEGEND

• Requires M3503LL/B/658-8032 Cable Terminator and Apple II SCSI Card.

A9M0320 or A3M0025 w/590-0037 require Super Serial Card BUT A9M0302 or A3M0025 w/590-0037 & 590-0550 doesn't (Buses Built In).

When using an ImageWriter II/LQ with the Apple IIe and cable part number 590-0555, the jumper on the Super Serial Card must be on "Modem".

Support Information Services
Copyright 1994, Apple Computer, Inc.

Keywords: ktable,cabinfo,review

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16383