



Tech Info Library

PowerBook: Cable Compatibility (8/96)

Article Created: 27 September 1994

Article Reviewed/Updated: 26 August 1996

TOPIC -----

This article provides cable compatibility information for Apple computer systems and a variety of Apple peripherals.

The left column lists the peripherals, the right column lists the cable required to connect all models of the Macintosh PowerBook computers with the exception of the PowerBook 200 and 2300 (Duo) series computers. PowerBook Duo computers may require a MiniDock or Duo Dock to utilize certain peripheral devices.

Part numbers which begin with a letter are finished goods part numbers which can be purchased from an Apple authorized reseller. The seven digit numbers are service part numbers which can only be purchased by an Apple authorized service center.

DISCUSSION -----

Begin_Table

Peripheral -----	Cable part number -----
AppleFax Modem	M0197/590-0552 (smoke)
Apple Personal Modem	
Apple Data Modem 2400	
Apple Modem 300	M0170/590-0197 & 590-0553
Apple Modem 1200	or 590-0121 & 590-0550
Apple ImageWriter II or II/L	M0197/590-0552 (smoke)
Apple ImageWriter LQ	LocalTalk optional
Apple ImageWriter Printer	590-0169 & 590-0553
Apple ImageWriter 15"	
LaserWriter, Plus, LaserWriter IInt, IIntx, IIIf, IIg LaserWriter Pro 600/630/810 LaserWriter 16/600 PS Personal LaserWriter NT, NTR	LocalTalk, Ethernet Optional for IIg, Pro 630, Pro 810, and 16/600 PS

Personal LaserWriter 320
LaserWriter Select 360

Personal LaserWriter LS M0197/590-0552 (smoke)
Personal LaserWriter 300
LaserWriter Select 300
LaserWriter Select 310
StyleWriter & StyleWriter II
StyleWriter 1200
Color StyleWriter/Color StyleWriter Pro
Color StyleWriter 2400

Any Apple (or third-party) SCSI
Peripheral device M2538LL/A (HDI-30 SCSI cable)•#&
Apple LaserWriter IIsc
Personal LaserWriter SC
AppleCD SC
Apple Hard Disk 20/40/80
Apple Tape Backup 40SC
Apple Scanner
Apple Color OneScanner
Apple Color Printer

LEGEND

- Requires M3503LL/B/658-8032 Cable Terminator in addition to the SCSI cable
- # Requires MiniDock or Duo Dock for use with PowerBook 200 and 2300 (Duo) computers
- & The M2538LL/A (HDI-30 SCSI cable) is not the same as the M2539LL/A - Apple HDI-30 SCSI Disk Adapter which enables use of the PowerBook 100 as an external hard disk with another Macintosh system.

End_Table

Article Change History:

- 26 Aug 1996 - Added begin and end table tags.
- 06 Jul 1995 - Updated ImageWriter I cable information.

Copyright 1994-96, Apple Computer, Inc

Keywords: ktable,cabinfo,kpbook,review

=====

This information is from the Apple Technical Information Library.

19960827 07:25:58.00

Tech Info Library Article Number: 16386