



# Tech Info Library

## Apple Telecom 2.0 and Earlier: PCI Bus Power Mac Issue (5/96).

Article Created: 28 June 1995

Article Reviewed/Updated: 23 May 1996

TOPIC -----

This article discusses compatibility issue between PCI bus Macintosh computers (like the Power Macintosh 9500) and Apple Telecom software.

DISCUSSION -----

Power Macintosh computers that ship with the PCI bus are not compatible with Apple Telecom 2.0 or earlier versions when used with a GeoPort Telecom Adapter. Users should upgrade to Apple Telecom 2.1 or later software.

If you are using a GeoPort Telecom Adapter on these Power Macintosh models, you must disable LocalTalk. To do this, disconnect any LocalTalk devices attached to the printer port (serial devices can remain attached).

Article Change History:

23 May 1996 - Updated for technical accuracy.

Copyright 1995-96, Apple Computer, Inc.

Keywords: supt

=====

This information is from the Apple Technical Information Library.

19960524 08:22:11.00

Tech Info Library Article Number: 18049