



# Tech Info Library

## Personal LaserWriter: No Refurbishment Kit

Article Created: 29 January 1992

Article Last Reviewed:

Article Last Updated:

TOPIC -----

Why doesn't Apple offer a refurbishment kit for the Personal LaserWriter printers?

DISCUSSION -----

The Personal LaserWriter engine life is rated at a minimum of 150,000 pages. The pick-up roller and separation pad each have a minimum rated life of 50,000 pages. However, since most users use the cassette tray, these parts will most likely last well beyond their 50,000-page rating. Also, the fuser assembly, laser scanner assembly, and other moving parts are expected to last the life of the engine. Therefore, there is no need for a refurbishment kit.

The LaserWriter and LaserWriter II engines have engine-life ratings that exceed the working life of several of their major modules (such as the fuser, cassette pick-up assembly, and transfer guide assembly). Therefore, refurbishment programs were created to ensure that proper maintenance is performed at the proper intervals.

Copyright 1992 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 9919