



Tech Info Library

LaserWriter Driver 5.0: Print Problems with a Mac 512Ke & Plus

Article Created: 8 February 1988
Article Last Reviewed: 31 October 1991
Article Last Updated: 18 October 1988

TOPIC -----

This article describes issues when using LaserWriter Driver and LaserWriter Pre version 5.0 on a Macintosh 512Ke or a Macintosh Plus.

DISCUSSION -----

If you are running LaserWriter Driver (and Prep) 5.0 on Macintosh 512Ke or Macintosh Plus, you may experience a problem with documents containing Bit-Mapped Graphics: the LaserWriter prints the document, then the Macintosh returns to the application, hangs, and must be restarted.

The problem is due to incompatibility between the driver file and the System and Finder files. The solution is to use a previous version of the LaserWriter Driver and LaserWriter Prep files, such as version 4.0, or move up to a more current version of the LaserWriter drivers, such as 5.2, 6.0, or 7.0 for the Macintosh Plus.

Copyright 1988 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2441