



Tech Info Library

LaserWriter Bridge v1.0: Do Not Rename (5/95)

Article Created: 15 September 1994

Article Reviewed/Updated: 16 May 1995

TOPIC -----

This article describes a problem which occurs if you rename the "LaserWriter Bridge" v1.0 file.

DISCUSSION -----

The LaserWriter (LW) Bridge is a Control Panel Device that allows a LaserWriter Select 360 to be bridged to an Ethernet network. The bridge resides on a host Macintosh that is connected to Ethernet. The Select 360 is linked to the host Macintosh through LocalTalk.

The name "LaserWriter Bridge" must NOT be renamed; otherwise, it will not function properly as follows: The dialog box that appears when you shutdown your computer running the bridge software, warning you that there are uncompleted print jobs in progress will NOT display.

Article Change History:

16 May 1995 - Added version number to article.

02 Dec 1994 - Changed access privileges.

Support Information Services

Copyright 1994-95, Apple Computer, Inc.

Keywords: ksts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16287