



Tech Info Library

Printing Postscript to DEC's LN03R Printer

This article last reviewed: 10 February 1988

When printing Postscript output from LaserWriter drivers to a DEC LN03R printer (LaserWriter Plus compatible) attached to a VAX, you may encounter an INVALID ACCESS ATTEMPT error for the SETDEFAULT TIMEOUTS command. When this command is removed, another error of UNDEFINED: NAME NOT FOUND is reported for the LEGAL command.

According to Adobe, you need to exit the server loop to use the setdefaulttimeout operator. The code is:

```
statusdict begin 0 exitserver
```

DEC's LN03 is LaserWriter-compatible from the Postscript side of things, but there are differences with respect to hardware options.

<None>

Keywords: <None>

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2516