

A/UX: Does Not Recognize ADB Port as a tty Port

| Article Created: 11 September 1991 |
|--|
| Article Change History |
| 08/31/92 - REVIEWED • For technical accuracy. |
| TOPIC |
| Does A/UX recognize the ADB (Apple Desktop Bus) port as a tty port |
| DISCUSSION |
| No, it doesn't. Copyright 1991, Apple Computer, Inc. |
| Keywords: <none></none> |
| |
| This information is from the Apple Technical Information Library. |
| 19960215 11:05:19.00 |
| Tech Info Library Article Number: 9203 |