



Tech Info Library

A/UX: Accessory Kit README File Correction

Article Created: 3 October 1989

Article Change History

08/31/92 - REVIEWED

- For technical accuracy.

TOPIC -----

The README file that comes with the A/UX Accessory Kit tells the user to phone 408-446-9836 for software patches.

I've tried this number several times without success. Is it the wrong number, or has the service not been turned on yet?

DISCUSSION -----

At present, the facility for providing A/UX software patches service has not been set up yet; the number 408-446-9836 is no longer in service. Please ignore the above information in the README file of the "A/UX System Setup and README" floppy disk at this time. We will announce the number as soon as this facility is completed.

Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 4744