



Tech Info Library

LaserWriter Pro 810: New atprint Allows Printing From AUX (5/94)

Article Created: 19 May 1994

TOPIC -----

When I am using A/UX 3.1 and a LaserWriter Pro 810. When I try using the "atprint" command, I get an "idle status" returned from the printer.

DISCUSSION -----

The "atprint" uses the Printer Access Protocol (PAP) to send data to the LaserWriter Pro 810. There is a new version of the "atprint" that fixes a problem in PAP that prevented A/UX from making a connection to the LaserWriter Pro 810 with A/UX 3.0.[12] or 3.1.

To locate Apple software updates, search the Tech Info Library for the article "Where To Find Apple Software Updates".

Support Information Services
Copyright 1994, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15387