



Tech Info Library

Apple IIc: Use Mouse Designed for IIc (11/94)

Article Created: 12 April 1991

Article Reviewed/Updated: 08 November 1994

TOPIC -----

I have a question concerning the "platinum" Apple IIc and a mouse. When I'm using the mouse, the cursor starts at the top-left corner and moves straight down to the bottom-left corner of the screen. Why?

DISCUSSION -----

You have come across an incompatibility in mouse timing. The mouse sold for the Apple IIc works properly, and mice received from service work properly. However, mice that came from Macintosh Plus systems sometimes work and sometimes not, depending on the manufacturer.

To assure proper operation, make sure you use a mouse that was designed for use with the IIc.

Article Change History:

08 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Copyright 1991-94 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7522