



Tech Info Library

Apple IIGS: Grappler Plus cards

This article last reviewed: 4 February 1987

Older Grappler Plus cards are not necessarily Apple IIGS compatible. Some of the older interface cards malfunction because of timing changes made to the IIGS slots, even though these changes were within Apple's specifications. The Grappler Plus card was designed before Apple even had those timing specifications.

On the Grappler Plus card at location U10, if the chip there is a 74LS373, then you have an old card and should contact Orange Micro. A 74LS374 is at U10 on the recent card.

<None>

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2128