



Tech Info Library

Apple IIc Serial Loopback Cable: Pinouts (10/94)

Article Created: 27 July 1985

Article Reviewed/Updated: 18 October 1994

TOPIC -----

This article describes the pinouts for the IIc serial loopback cable.

DISCUSSION -----

Below are the pin configurations for the Apple IIc serial loopback cable:

Modem port		Printer port
1	to	5
5	to	1
2	to	4
4	to	2

Ground the connector shields together.

Article Change History:

18 Oct 1994 - Reviewed for technical accuracy, revised formatting.

Support Information Services

Copyright 1988-94 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1218