

## Apple IIGS: Users Should Upgrade to PrintShop GS 1.1

This article last reviewed: 2 November 1989 TOPIC ------This article describes why and how to get an upgrade for Printshop GS. DISCUSSION ------Versions prior to 1.1 of Broderbund's PrintShop GS are incompatible with the new Apple IIGS ROMS. The fix is for the customer to send the PrintShop disk back to Broderbund (address is on the disk label, Attn: Software), along with a receipt of purchase and a letter stating that you would like to upgrade to version 1.1. Copyright 1989 Apple Computer, Inc. Keywords: <None> ------This information is from the Apple Technical Information Library. 19960215 11:05:19.00 Tech Info Library Article Number: 4777