



Tech Info Library

AppleTerm: Using it with a IIc or IIe

If the AppleTerm program refuses to address a modem when a printer is attached to another port or card, check that the printer is turned on and selected. If so, everything should work right. If the printer isn't turned on or selected, and is yet still connected to the port or card, then the modem won't work: the program sends an initialization procedure to the printer, and if it doesn't get something back from the printer firmware, it will hang. Usually what happens is that a "@" appears in the upper left corner of the screen.

NOTE: This same problem will occur if the printer interface isn't on an Apple Super Serial Card: AppleTerm will only acknowledge an Apple SSC.
Apple Technical Communications

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 891