



Tech Info Library

Apple III Drive: Parts Not Interchangeable with DuoDisk, Disk II

Article Created: 13 August 1991

Article Last Reviewed:

Article Last Updated:

TOPIC -----

I have some spare Apple III computers equipped with 5.25 disk drives. Is it possible to use the drive mechanisms or other parts from the disk drive in the Apple III computers and replace them with parts in the DuoDisk drive?

DISCUSSION -----

The drive mechanism from the Apple III drive is not compatible with either the Disk II or the DuoDisk, so you would have to purchase the mechanical assembly for the DuoDisk. The part number for that drive's mechanical assembly is 661-72128

Copyright 1991 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8745