



Tech Info Library

GeoPort Adapter: Conflict with DOS Compatibility Card (9/96)

Article Created: 22 May 1995

Article Reviewed/Updated: 25 September 1996

TOPIC -----

When I try connecting to the GeoPort Telecom Adapter from my Power Macintosh DOS Compatibility Card, the DOS Compatibility Card hangs. If I use my Macintosh communication applications or temporarily use an external modem with the DOS Compatibility Card, everything works properly.

DISCUSSION -----

The GeoPort has not been tested with any version of Apple Computer's DOS Compatibility products, and it is not supported in this environment.

Affected Products

- DOS Compatibility Card for Power Macintosh 6100 or Performa 6100 Series.
- 7-in. and 12-in. PC Compatibility Cards for Power Macintosh Computers.
- GeoPort Telecom Adapter

This article appeared in the Information Alley on 26 September 1996.

Article Change History:

25 Sep 1996 - Changed distribution status.

22 May 1996 - Added PC Compatibility Card info.

04 Apr 1996 - Updated article discussion.

Copyright 1995-96, Apple Computer, Inc.

Keywords: kwindows,knts, kalley

=====

This information is from the Apple Technical Information Library.

19960927 07:25:58.00

Tech Info Library Article Number: 17797