



# Tech Info Library

## ARA, Performa 611x, and Global Village Gold II Modem (5/95)

Article Created: 27 February 1995

Article Reviewed/Updated: 18 May 1995

### TOPIC -----

This article describes a problem with users of the Performa 611x computer typically choosing the wrong Apple Remote Access (ARA) connection script, GV TP Gold/Silver. This modem script does not work with the Gold II modem that ships with the Performa 611x. However, the correct connection script is on the computers hard disk.

### DISCUSSION -----

The Performa 611x like most Performa computers, comes with a modem. This modem is a TelePort Gold II for Performa from Global Village. It has both 14,400 bps send and receive fax plus 14,400 bps data. This modem also requires a special connection script or CCL for ARA. Here is the hard drive path to the CCL:

```
Hard Disk:Applications:GV TelePort Gold II:Scripts:ARA 2.0 Script:GV TelePort Gold II for ARA 2.0
```

The CCL, GV TelePort Gold II for ARA 2.0, must be placed in the extensions folder within the System Folder, and chosen in the Remote Access Setup control panel for the modem to work properly with ARA.

### Article Change History:

18 May 1995 - Corrected path to the CCL.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Keywords: supt

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17282