



Tech Info Library

Token Ring NB/c Card: Token Ring Control Panel Not Needed-3/95

Article Created: 9 September 1994

Article Reviewed/Updated: 27 March 1995

TOPIC -----

The Apple Token Ring NB/c Card Icon does not appear in the Token Ring Control Panel. The problem is consistent with six different Power Macintosh 6100 computers. The same software works fine in the Power Macintosh 7100 and 8100 computers, although the installed cards are Apple Token Ring 4/16 NB Cards. What is the problem and how does one switch to Token Ring?

DISCUSSION -----

The Token Ring control panel does not work with the 7 inch Token Ring NB/c Card. Simply switch over to TokenTalk in the Network Control Panel and set the jumper on the card to configure speed. You must have done a "drag" install of the control panel since the installer for network software does not install this control panel for this particular card.

Article Change History:

27 Mar 1995 - Made minor corrections.

Support Information Services

Copyright 1994-95, Apple Computer, Inc.

Keywords: knts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16247