



Tech Info Library

Global Village Modem: No Max Throughput Checkbox (11/96)

Article Created: 24 September 1996

Article Reviewed/Updated: 12 November 1996

TOPIC -----

I have a Macintosh Performa computer with a Global Village modem. I do not see a "Max Throughput" check-box in the Teleport control panel. Why?

DISCUSSION -----

The "Max Throughput" checkbox is only available on computers that support Direct Memory Access (DMA). Currently, only the Macintosh Performa 6100 and 6400 series computers support this capability, and only the 6400 is bundled with a modem for which this is an option.

The feature requires that the functionality be installed in hardware; there is not a software-based patch to implement DMA. Without DMA support, Macintosh computers are limited to a 57.6 Kbaud throughput rate.

This article was published in the Information Alley on 26 September 1996.

Article Change History:

12 Nov 1996 - added alley info.

Copyright 1996, Apple Computer, Inc.

Keywords: kalley

=====

This information is from the Apple Technical Information Library.

19961113 08:31:20.00

Tech Info Library Article Number: 20447