



# Tech Info Library

## Apple PCI Token Ring Card: Does Not Work With LLC 2 (5/96)

Article Created: 24 May 1996

TOPIC -----

I cannot seem to get 802.2 Logical Link Control version 2 (LLC 2) support when using Apple's PCI Token Ring card. I am using Attachmate's IRMA for the Mainframe 4.0.5. Attachmate tells me that Apple's PCI Token Ring card does not support this protocol. I tried to use the MacMainframe software and the LLC 2 section is grayed out.

What is wrong? Does the Apple PCI Token Ring Card not support LLC 2?

DISCUSSION -----

No, Apple's PCI Token Ring card does NOT support LLC 2. Apple has no plans at this time to add support for LLC 2.

Copyright 1996, Apple Computer, Inc.

Keywords: supt

=====  
This information is from the Apple Technical Information Library.

19960528 07:25:21.00

Tech Info Library Article Number: 19861