



Tech Info Library

(Lisa)Mac XL : LisaTest V.2.2 - Error 3 in Step 7

Article Created: 27 September 1985
Article Last Reviewed: 17 July 1992
Article Last Updated:

PROBLEM DESCRIPTION: Lisa Test Error number 3 displayed during Step 7 when using version 2.2 indicates a "Parallel Port VIA Interrupt Failure".

CAUSE: The hard disk may be formatted for Macintosh software or have been partitioned for a shared Macintosh and Lisa environment when the 7/7 office system was installed. LisaTest version 2.2 does not operate with these configurations.

CURE: Use LisaTest 3.0 or later for Macintosh formatted hard disks. Use Mac XL/Lisa Modification Test Version 1.0 or later for Square Pixel Screen Driver.

If this cure does not resolve the problem, go to the Lisa 2/Macintosh XL Technical Procedures, for the troubleshooting procedures for this product.

Copyright 1988 Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1690