



Tech Info Library

Canon SX Engine's Life Expectancy Is 300,000 Pages

This article last reviewed: 11 January 1988

The Canon SX LaserWriter engine has a life expectancy of 300,000 pages. Service is required after 100,000 pages, at which time the following parts and/or assemblies should be replaced:

- Fuser Assembly
 - Pick-up Roller Unit
 - Transfer Guide Unit
 - Transfer Corona Assembly
 - Ozone Filter
- <None>

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2437