



Tech Info Library

LaserWriter: Possible Causes of Curved/Skewed Straight Lines

This article last reviewed: 15 February 1988

If a line drawn as a straight vertical lines on the Macintosh's screen is not a perfectly vertical line when printed on a LaserWriter, it may be due to:

- the type of paper stock being used
- a problem with the paper feed assembly
- a faulty laser scanner unit

If the line is straight but not perfectly vertical when printed, it may be due to the skew adjustment.

<None>

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2644