



Tech Info Library

LaserWriter Pro 600 and 630: Maintenance Intervals (7/93)

Article Created: 28 July 1993

TOPIC -----

Are there any parts or modules that should be replaced at regular intervals to maintain optimal print quality on the LaserWriter Pro 600 and 630?

DISCUSSION -----

There is no refurbishment kit currently available for the LaserWriter Pro 600 and 630, however, several parts should be replaced at regular intervals if a deterioration in print quality or paper handling is noticed. Use the table below as a guide for determining when the consumable parts should be replaced.

Description	Part Number	Expected Life
Fuser assembly	661-0802 (110/115V)	200,000 pages
	661-0803 (220/240V)	200,000 pages
Multi-purpose pickup roller	922-0281	200,000 pages
Cassette pickup roller	922-0280	200,000 pages
Separation pad	922-0286*	200,000 pages
Transfer roller	922-0205	200,000 pages
Fan	922-0202	25,000 hours

* The separation pad is included with the multipurpose tray guide assembly.
Copyright 1993, Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12728