Macintosh II: Always Keep It Horizontal

Tech Info Library Article Number: 2525

Article Created: 3 February 1988 Article Last Reviewed: 30 June 1992 Article Last Updated:
TOPIC
Can I use my Macintosh II in a vertical orientation?
DISCUSSION
A Macintosh II, or Macintosh IIx and Macintosh IIfx, should always be kept horizontal.
Standing it on end - voids the warranty - defeats the cooling design - will eventually damage the main unit.
The above remains true even if the required 4 to 6 inches of clearance is maintained around the vents. Copyright 1989 Apple Computer, Inc.
Keywords: <none></none>
This information is from the Apple Technical Information Library.
19960215 11:05:19 00