



Tech Info Library

Apple CD-ROM Explorer Disk: Using with Macintosh IIsi

Article Created: 17 April 1991
Article Last Reviewed: 15 July 1992
Article Last Updated: 29 July 1992

TOPIC -----

I have a Macintosh IIsi with the 12-inch RGB display and an AppleCD SC. The problem is my CD-ROM Explorer disk included with my AppleCD SC was designed for a 13-inch RGB monitor. Also, the HyperCard stacks on the CD-ROM Explorer are incompatible with HyperCard 2.0, the version required when using 6.0.7 system software.

My questions are:

- 1) Is Apple going to revise the CD-ROM Explorer disk?
- 2) If yes, what is the upgrade policy and how do I get a copy?

DISCUSSION -----

The CD-ROM Explorer HyperCard stacks are compatible with HyperCard 1.2.5 and HyperCard 2.0 under Macintosh System Software 6.0.7.

As of July 1992, the CD-ROM Explorer disk is no longer included with Apple CD-ROM drives.

Copyright 1991, 1992 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7156