



Tech Info Library

ImageWriter I: Compatible with Newer Macintosh Models (2/96)

Article Created: 15 April 1991

Article Reviewed/Updated: 5 February 1996

TOPIC -----

I am having difficulty using a Macintosh Classic with a wide carriage ImageWriter I. Are there any known incompatibilities with old ImageWriter printers and the new computers or system software?

DISCUSSION -----

There are no known compatibility problems with the ImageWriter I and Macintosh computer with DIN 8 serial ports, if the current ImageWriter driver and the proper cables are used.

The current ImageWriter driver is version 2.7 for System 6 users and version 7.0.1 for System 7.x users. The correct cable configuration is to use the original Macintosh to ImageWriter DB-9 to DB-25 cable, part number 590-0169, with the DB-9 to Mini DIN 8 Macintosh Peripheral Adapter cable, part number 590-0553.

When using these cables and the current ImageWriter driver, the printer should work just fine.

Article Change History:

05 Feb 1996 - Made minor change.

06 Jul 1995 - Updated part numbers to reflect current models

Support Information Services

Copyright 1991-96 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7261