

Macintosh IIvx: IIci Cache Card, Accelerator Slot Incompatible

| Article Created: October 19, 1992 |
|---|
| TOPIC |
| Can I use the IIci Cache Card in the new Accelerator slot? |
| DISCUSSION |
| No. The Macintosh IIci Cache Card is incompatible with the new accelerator slot. The accelerator slot does not accommodate cache-only cards. |
| Macintosh IIvx has its cache architecture on the logic board, which means the accelerator slot is left open for a third-party accelerator card. |
| Accelerator cards such as 50 MHz 68030s or cards based on 68040s are meant for this slot. Copyright 1992, Apple Computer, Inc. |
| Keywords: <none></none> |
| ======================================= |
| This information is from the Apple Technical Information Library. |
| 19960215 11:05:19.00 |
| Tech Info Library Article Number: 10773 |