



Tech Info Library

Apple Early Language Connections: LC 575 Use CD-ROM 5.0 (9/94)

Article Created: 19 September 1994

TOPIC -----

I've had to reinstall the Apple Early Language Connections software on my Macintosh LC 575 computer, and now I cannot get the CD-ROM to recognize any CD ROMS that I put into the computer.

DISCUSSION -----

Version 4.0 of the Apple Early Language Connections CD uses version 4.0.3 of the CD-ROM drivers. The Macintosh LC 575 and other computers that use the AppleCD 300i Plus CD-ROM Drive, require version 5.0 of the drivers. In order to install the Apple Early Language Connections CD on a Macintosh LC 575 computer, follow these steps:

- 1) Insert the Apple Early Language Connections CD and reinstall the software.
- 2) Restart your Macintosh
- 3) Place the Macintosh LC 575 Install Me First CD in the computer.
- 4) Use the Custom install option to install version 5.0 of the CD-ROM software.
- 5) Restart your Macintosh

Once the new CD-ROM drivers are installed, you can use the CD-ROM drive.

Note: Version 4.1 of the Apple Early Language Connections CD uses version 5.0 of the CD-ROM software, so you don't need to custom install the CD-ROM drivers.

Support Information Services
Copyright 1994, Apple Computer, Inc

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16321