



# Tech Info Library

## Macintosh LC: Use EtherTalk 2.5 or higher

Article Created: 14 August 1991  
Article Last Reviewed: 23 July 1992  
Article Last Updated:

TOPIC -----

I cannot get EtherTalk 2.0.1 to work on my Macintosh LC.

DISCUSSION -----

The Macintosh LC requires EtherTalk 2.5 or higher.  
Copyright 1991, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8901