



Tech Info Library

LC 575, Quadra 650: Maxtime Cable Message Upon Startup (6/94)

Article Created: 10 March 1994

Article Reviewed/Updated: 29 June 1994

TOPIC -----

In booting up a Quadra 650 or Macintosh LC 575, a message that says "Sending handshake byte in postburn. Please plug in Maxtime cable for postburn." may be generated.

This article describes how to get rid of this message.

DISCUSSION -----

This message occurs when the burn-in software is not erased off of the hard drive at the factory prior to shipping.

To remove the software:

- 1) Boot from the Disk Tools diskette or the InstallMeFirst CD.
- 2) Trash the files in the Startup Items folder.

Or another alternative is to reinitialize the drive and reinstall system software.

Article Change History:

- 14 April 1994 - Added Quadra 650 to the article title and discussion.
- 29 June 1994 - Cleaned up the discussion.

Support Information Services
Copyright 1994, Apple Computer, Inc

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 14859