



Tech Info Library

PowerBook: Low Temperature Storage (4/95)

Article Created: 1 November 1991

Article Reviewed/Updated: 03 April 1995

TOPIC -----

What problems could be caused if the temperature falls below the minimums listed in the PowerBook specs?

DISCUSSION -----

The main concerns are:

- the liquid crystal display (LCD) material freezing

and

- moisture in the hard disk drive freezing.

The drive can be thawed out however, damage to the LCD would typically require replacement of the display.

Article Change History:

03 Apr 1995 - Reviewed for technical accuracy.

Support Information Services

Copyright 1991-95, Apple Computer, Inc.

Keywords: kpbook

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 9122