



Tech Info Library

PowerBook 100: When It Won't Recognize Third-Party Drive (8/92)

Article Created: 30 October 1991

Article Reviewed/Updated: 3 August 1992

TOPIC -----

My PowerBook 100 won't recognize non-Apple hard drives.

DISCUSSION -----

Are you using one terminator in the chain? This means either an external terminator or a built-in terminator to the third-party device.

The termination on the PowerBook 100 hard disk drive isn't strong enough to support the bus. So if the third-party device doesn't have an internal terminator, you need to provide an external terminator.

Support Information Services
Copyright 1991, Apple Computer, Inc.

Keywords: KPBook

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 9298