



Tech Info Library

PowerBook RAM Upgrades: Don't Remove Rubber Heat Sinks 11/92

Article Created: November 9, 1992

TOPIC -----

I have a third-party 4MB RAM upgrade I want to install in a PowerBook, but it doesn't fit because four chips on the daughterboard have a large 1/4- inch piece of rubber on top of them. What is the rubber for, and is it safe to remove it?

DISCUSSION -----

The pieces of rubber on the chips are heat sinks. It is essential that you leave them in place, because if you remove them:

- Too much heat will be generated internally.
- Warranty coverage is voided.

Apple has given strict design guidelines to third-party developers, and we suggest that customers get verification that products meet Apple specifications.

Support Information Services
Copyright 1992, Apple Computer, Inc.

Keywords: KPBOOK

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11005