



Tech Info Library

PowerBookControl Strip Moves When Changing Resolution (5/96)

Article Created: 13 May 1996

TOPIC -----

PowerBooks with System 7.5.2 or later may experience a cosmetic problem with the Control Strip. The problem is that when the PowerBook goes from a lower resolution display to a higher resolution display, the Control Strip may appear half-way up the screen.

DISCUSSION -----

This will only happen if the Control Strip is opened, closed, or moved while it is at the lower resolution. The workarounds are either not to adjust the Control Strip while it is at the lower resolution, or to simply drag the Control Strip back to the desired position while holding down the Option key when the problem occurs.

Apple is currently investigating this problem and hopes to have it fixed in a future system update.

Copyright 1996, Apple Computer, Inc.

Keywords: kpbook,sys75

=====

This information is from the Apple Technical Information Library.

19960513 15:50:59.00

Tech Info Library Article Number: 19777