



Tech Info Library

Macintosh Performa 6100 Series: Low Sound Volume (8/95)

Article Created: 28 August 1995

TOPIC -----

The sound level from the internal speaker seems low on my Macintosh Performa 6100 series computer. What is causing this and what can I do to get higher volume?

DISCUSSION -----

You should first check the volume levels in the Sound control panel. Open the Sound control panel and adjust the volume in both the Alert sounds and Volumes options.

The internal speaker is located directly underneath the computer. Make sure that your computer is on a flat surface with no obstructions. Paper or other material directly under the computer can dampen the sound.

Another way to get louder sound is to connect external speakers. Many monitors have speakers that can be connected to the audio-out port of your computer.

The following computers are in the Macintosh Performa 6100 series: Performa 6110, Performa 6112, Performa 6115, Performa 6117, and Performa 6118.

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 18491