



Tech Info Library

DAL 1.2: Bug in MacMainFrame 3.2 in CUT Mode

Article Created: March 9, 1991

Article Change History

07/10/92 - REVIEWED

- For technical accuracy

TOPIC -----

There is a known bug with MacMainFrame 3.2 (CUT only) and DAL 1.2.

DISCUSSION -----

If your controller runs in DFT mode, use it. Otherwise, you'll need the latest Avatar release 3.3x. The 3.3x MacMainFrame product works fine under both CUT and DFT with DAL at release 1.2.

Copyright 1991 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7169