

EtherPort Installer Upgrade for System 6.0.4 & 6.0.5

This article last reviewed: 23 May 1990

TOPIC -----

This article contains information on an upgrade for Novell's EtherPort installers.

DISCUSSION -----

Novell has updated their installers to work with System Software 6.0.4 and 6.0.5. You can obtain the updated installers from Novell, or install the drivers on a system running System Software 6.0.4 or 6.0.5 using this workaround:

To install Novell EtherPort drivers on systems running System Software 6.0.4 or 6.0.5:

1) Start up the system from a 6.0.4 or 6.0.5 System Tools disk.

2) Eject the Tools disk.

3) Insert the Novell Installer disk and execute the Installer from that disk.

Be prepared to swap the disks a few times when prompted by the Installer program. This procedure differs from the normal install procedure of starting up from the Installer disk.

To obtain the new Installer disk, contact Novell. Note that there are two different updated versions of the Installer program for the two different Novell EtherPort II cards distributed:

Version 2.5 Rev e This is for the "Intel" or long EtherPort II card. Version 3.25 Rev b This is for the "National Semiconductor" or short EtherPort II card.

For more information, search under: "Novell" Copyright 1990 Apple Computer, Inc.

Keywords: <None>

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 5550